

July 2024

To: All Morbark, LLC-affiliated Dealers, [REDACTED]

Subject: **Notification of Safety Recall and Recall Remedy Instructions for 24V-342**
Certain Morbark, LLC (“Morbark”) Eger Beaver 1821, 1922, and 2131 brush chippers
manufactured in 2023 – 2024
Engine Fuel lines

REASON FOR THIS SAFETY RECALL:

On May 15, 2024, Alamo Group Inc., filed a Defect Information Report with the National Highway Traffic Safety Administration (NHTSA) informing the agency that certain Eger Beaver brush chipper vehicles manufactured by Morbark, have engine fuel lines that are not rated for the necessary fuel pressure required by the engine. An engine fuel line rated below the necessary pressure rating may burst and leak fuel, increasing the risk of a fire.

AFFECTED VEHICLES:

[REDACTED]	EB 1821/M15R
[REDACTED]	EB 1821/M15R

REMEDY:

Remedy parts are available now. Dealers will install engine fuel lines that are rated for the pressure required by the engine. This service must be performed on all affected vehicles **at no charge** to the vehicle owner. Attached please find the service procedure for completing this repair. The repair takes about 1 hour to complete.

REIMBURSEMENT:

Alamo Group will reimburse dealers for performing this remedy.

OWNER LETTER MAILING DATE:

Alamo Group will notify owners of this safety recall by letter mailed on or before July 12, 2024.

CUSTOMER CONTACTS:

Dealers should repair any Morbark Eger Beaver vehicles covered by this safety recall that arrives at their dealerships, whether or not the owner has received a safety recall letter. The Morbark Service Department (at 989-866-2381), is available to support you in executing a customer-friendly process for remedying these vehicles.

NEW VEHICLES IN DEALER INVENTORY:

Dealers may have covered Morbark Eger Beaver vehicles in their inventory. **It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect is remedied.** Violation of this requirement by a dealer could result in a civil penalty against the dealer. Accordingly, you must remedy any covered Morbark Eger Beaver vehicles in your new vehicle inventory before delivery.

In addition, we request that you remedy before delivery into commerce under a sale or lease any covered pre-owned Morbark Eeger Beaver vehicles in your inventory.

QUESTIONS & ASSISTANCE:

For questions and assistance, including help in identifying whether any vehicles in your inventory are covered by this safety recall, please contact the Morbark Service Department (at 989-866-2381).

Thank you for your attention to this important matter.

Sincerely,

A handwritten signature in black ink, appearing to read "M Stanton", written in a cursive style.

**Michael Stanton
General Manager
Morbark, LLC**

Attachment: Service Procedure