ARA7 Recall Campaign - Replace shift cable

ARA7 Recall Campaign - Replace shift cable

ID Number ARA7

Affected Models 718 Boxster / Cayman (982)

Affected Model Years 2024
VIN List Attached

Number of affected vehicles 14

realises of anected verticies

Issue Description

What should Porsche Centers do?

What will Porsche do?

On the affected vehicles, the cable sleeve on the shift cable of the PDK can potentially be damaged if the rework is not carried out in the correct manner.

This may result in the transmission not being shifted into the parking position (P) as intended. As a result, the vehicle may roll away although parking gear has been selected.

To prevent this from happening, the shift cable must be replaced.

Please arrange for the remedy to be carried out as soon as possible on affected vehicles.

As of the time of this posting (6/14/24) the repair is immediately available.

Vehicles will have the remedy performed once it is available.

As of the time of this posting (6/14/24) the repair is immediately available.

TI Number No. 87-24

Customer Letter To be posted at a later date.

Customer Reactive Statement

The safety of our customers and quality of our vehicles are of paramount importance. We recently identified 14 Model Year 2024 718 vehicles that need their transmission shift cables replaced free of charge to the customers, who will be notified shortly. No incidents have been reported in the United States.

1

Attachments

1. VIN_List_Report_ARA7_2024-06-14_V2.xlsx