

Reference Number: GCUS-3-3280

N242448540 - Safety Recall - Right Front Lower Control Link Fracture - Inspection Procedure

GENERAL MOTORS

DCS6934

URGENT - DISTRIBUTE IMMEDIATELY

Date: June 28, 2024

Subject: N242448540 - Safety Recall

Right Front Lower Control Link Fracture

Inspection Procedure Available

Models: 2024 Chevrolet Blazer EV

General Motors is releasing Safety Recall N242448540 today.

What Should Dealers Do: Dealers should review IVH or the Dealer Maxis reports for VINs in their inventory. Dealers can view the attached bulletin and it will also be displayed in Service Information tomorrow.

The parts needed to complete the required repair are not yet available. All VINs have been placed in "Incomplete. Remedy Not Available" status.

This bulletin contains an inspection procedure for both dealer inventory and customer vehicles. Vehicles (both dealer inventory and customer owned) that pass this inspection procedure should be closed using the "Inspect Only – Vehicle Passed Inspection (No Further Action Required)" labor code 9107569.

It is estimated that a very small percentage of the involved vehicles will fail the inspection and require part replacement. Vehicles that do not pass the inspection must be held and not delivered to customers until the repair is completed. The bulletin will be updated when the remedy and required parts become available, at which time those vehicles can be repaired, closed, and delivered.

Frequently Asked Questions Document (FAQs)

Attached to this message you will find a document that addresses the most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

A list of vehicles in dealer inventory or in transit is attached to this message. Note: this list is only accurate at the time of report creation and all VINs should be validated in IVH prior to repair.

END OF MESSAGE