

October 2024

To: All Morbark, LLC-affiliated Dealers

Subject: **Notification of Safety Recall and Recall Remedy Instructions for 24V-627**
Certain Morbark, LLC (“Morbark”) Eger Beaver 1821, 2230, and 2131 brush chippers and M20 whole tree drum chippers manufactured in 2018 – 2024
Power Distribution Module (PDM) Wiring

REASON FOR THIS SAFETY RECALL:

On August 21, 2024, Alamo Group Inc., filed a Defect Information Report with the National Highway Traffic Safety Administration (NHTSA) informing the agency that certain Eger Beaver brush chipper and M20 whole tree drum chipper vehicles manufactured by Morbark, have loose wiring connecting the PDM to the engine. Loose PDM wiring may come into contact with the PDM plate causing arcing which may ignite byproduct from forestry operations, increasing the risk of a fire.

AFFECTED VEHICLES:

Make and Model	Number of vehicles	Production Period
Morbark: EB1821 EB2230 EB2131 M20	135	June 1, 2018 – August 22, 2024

REMEDY:

Remedy parts are available now. Dealers will apply a resin that permanently affixes the nut securing the wiring to the PDM. This service must be performed on all affected vehicles **at no charge** to the vehicle owner. Attached please find the service procedure for completing this repair. The repair takes about 30 minutes to complete.

REIMBURSEMENT:

Alamo Group will reimburse dealers for performing this remedy. Dealers should submit a warranty claim for this remedy in the Morbark warranty system.

OWNER LETTER MAILING DATE:

Alamo Group will notify owners of this safety recall by letter mailed on or before October 18, 2024.

CUSTOMER CONTACTS:

Dealers should repair any Morbark Eger Beaver and M20 vehicles covered by this safety recall that arrives at their dealerships, whether or not the owner has received a safety recall letter. The Morbark Service Department (at 989-866-2381), is available to support you in executing a customer-friendly process for remedying these vehicles.

NEW VEHICLES IN DEALER INVENTORY:

Dealers may have covered Morbark Eger Beaver or M20 vehicles in their inventory. **It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect is remedied.** Violation of this requirement by a dealer could result in a civil penalty against the dealer.

Accordingly, you must remedy any covered Morbark Eger Beever or M20 vehicles in your new vehicle inventory before delivery.


In addition, we request that you remedy before delivery into commerce under a sale or lease any covered pre-owned Morbark Eger Beever or M20 vehicles in your inventory.

QUESTIONS & ASSISTANCE:

For questions and assistance, including help in identifying whether any vehicles in your inventory are covered by this safety recall, please contact the Morbark Service Department (at 989-866-2381).

Thank you for your attention to this important matter.

Sincerely,

A handwritten signature in black ink, appearing to read 'M Stanton', written in a cursive style.

Michael Stanton
General Manager
Morbark, LLC

Attachment: Service Procedure