



DATE: October 2024
TO: Micro Bird Distributors
SUBJECT: Recall 24-111-GUC / NHTSA Recall 24V706

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Micro Bird has decided that a defect, which relates to motor vehicle safety, exists in a 2023 G5 vehicle equipped with an Oliva Torras second air conditioning compressor kit.

In the recalled vehicle, the engine drive belt tensioner provided with the Oliva Torras compressor kit may not be strong enough, resulting in the tension in the engine drive belt to decrease. If it happens, the engine drive belt may move on the pulleys and even become dislodged. If the engine drive belt comes loose, critical accessories, such as the power steering, the alternator, the water pump, may stop working, increasing the risk of loss of control, loss of power or engine overheating, increasing the risk of a crash and/or fire.

To complete this recall, owners will contact you to make an appointment to have their vehicle(s) corrected. Please make sure to order the required parts to have them on hand at the time of the appointment. It may be possible to order a few in advance.

We request that you apply for reimbursement via the GOLS claim system with detailed invoices, a list of repaired vehicles so we can update our files.

Micro Bird Corporation will provide correction instructions and parts, as well as reimburse labor to mitigate this recall at no charge.

The allotted time to correct the defect is 90 minutes per vehicle.

Important: We want to remind you that recalled vehicles must be corrected before you sell, lease, or deliver them; vehicles returned at the end of a lease must be corrected before they can be offered for sale as used vehicles.

We apologize for any inconvenience this situation may cause and we thank you for your cooperation.