

24PBH – Safety Recall – Cummins X15 Engine Fuel Pump

 [Edit](#)  [Clone](#)

Number

24PBH / NHTSA: 24V-789 / Transport Canada: 2024-630 / Cummins: C7083

Supplier

Cummins

Description

24PBH – Safety Recall – Cummins X15 Engine Fuel Pump

Date

11/15/2024

What's New

Safety Recall

Reference Cummins Safety Recall C7083

Cummins alerted Peterbilt to a defect which relates to motor vehicle safety that may affect certain Cummins X15 engines.

Refer to **Cummins Safety Recall C7083** for repair information.

Introduction

Cummins alerted Peterbilt to a defect which relates to motor vehicle safety in certain Model Year 2025 567, 579, and 589 vehicles manufactured from 06/17/2024 through 09/04/2024 with Cummins X15 engines.

The Fuel Pump Heads installed on some of the engines in the suspect population may have been built using low fatigue strength parts, making them susceptible to fracture. If a Fuel Pump Head fractures, an external fuel leak and sudden loss of fuel pressure may occur, potentially causing the engine to stall without the ability to restart. An engine stall without the ability to restart may increase the risk of a crash.

Refer to **Cummins Safety Recall C7083** for repair information.

Situation

2,508 (2,351 US and 157 Canada) Model Year 2025 Peterbilt 567, 579, and 589 chassis built from 06/17/2024 through 09/04/2024 equipped with certain Cummins X15 engines.

Resolution

Safety Recall

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their

chassis is on the list.

2. In Service Management, select campaign C7083 to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service Management.
3. If you are not using Service Management to start repair orders, review SIR for "Complete" or "In Process" next to the "C7083" Cummins campaign code prior to performing this repair.
4. Follow the procedures in Cummins C7083 Safety Recall to replace the fuel hoses. Go to Cummins QuickServe and refer to the Cummins Recall – C7083

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

Go to Cummins QuickServe and refer to the Cummins Recall C7083. File warranty claims through the Cummins warranty system. SIR will indicate chassis involved in this recall with the designator of "C7083" in the campaign field.

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

Please refer to Cummins QuickServe for repair procedure. Reference Cummins Recall C7083.

Links

[24PBH Chassis List Bulletin](#)

[C7083 Cummins US Customer Letter](#)

[C7083 Cummins CA Customer Letter](#)

[C7083 Cummins CA Customer Letter - French](#)

[Cummins Safety Campaign Notification C7083](#)