

24PBK - PACCAR 20k Steer Axle Steer Arm and Tie Rod Arm Bolt Torque

Number

[Edit](#) [Clone](#)

24PBK / NHTSA Recall Number: 24V908 / Transport Canada Recall Number: 2024-732

Description

PACCAR 20k Steer Axle Steer Arm and Tie Rod Arm Bolt Torque

Date

12/12/2024

What's New

Interim Safety Recall

Specific 2024 Peterbilt model 367, 389, 548, and 2024-2025 Peterbilt 520 and 567 chassis equipped with a PACCAR 20k Steer Axle have been identified as having steer arm and/or tie rod arm fasteners that may be improperly torqued and can be at risk of failing. If both fasteners in either steering arm or tie rod arm fail, there may be a loss of steering control, which could increase the risk of a crash.

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Safety Recall start date: 12/12/2024

Introduction

Specific 2024 Peterbilt model 367, 389, 548, and 2024-2025 Peterbilt 520 and 567 chassis equipped with a PACCAR 20k Steer Axle have been identified as having steer arm and/or tie rod arm fasteners that may be improperly torqued and can be at risk of failing. If both fasteners in either steering arm or tie rod arm fail, there may be a loss of steering control, which could increase the risk of a crash.

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Safety Recall start date: 12/12/2024

Situation

36 (33 U.S. and 3 Canada) Model Year 2024 Peterbilt 367, 389, 548, and 2024-2025 Peterbilt 520 and 567 chassis built from 01/27/2023 to 2/5/2024 and equipped with a PACCAR 20k Steer Axle.

Resolution

Interim Safety Recall

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Parts

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Links

[24PBK - Chassis List](#)

[24PBK - INTERIM US Customer Letter](#)

[24PBK - INTERIM Canadian Customer Letter \(English\)](#)

[24PBK - INTERIM Canadian French Customer Letter](#)