This notice applies to your vehicle,

32B/NHTSA 24V-209

**LOGO** 

# **VEHICLE PICTURE**

## YOUR SCHEDULING OPTIONS

- 1. RECOMMENDED OPTION
  Call your authorized Chrysler /
  Dodge / Jeep<sub>®</sub> / RAM Dealership.
- 2. Call the FCA Recall Assistance Center at 1-800-853-1403. An agent can confirm part availability and help schedule an appointment.
- 3. Visit recalls.mopar.com, scan the QR code below, or download the Mopar Owner's Companion App.

**QR Code** 

Get access to recall notifications, locate your nearest dealer, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity. The last eight characters of your VIN are provided above.

## **DEALERSHIP INSTRUCTIONS**

Please reference Safety Recall 32B.

# IMPORTANT SAFETY RECALL

#### Manufacturer label

Dear [Name],

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

FCA US LLC has decided that certain [2024 model year (GG) Dodge Hornet] vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 110 - Tire selection and rims.

It is extremely important to take steps now to repair your vehicle to ensure the safety of you and your passengers.

#### WHY DOES MY VEHICLE NEED REPAIRS?

Your vehicle [1] may have been built with a manufacturer label that is missing rim and tire size designation information. Relying on incorrect rim and tire size designation information can result in the use of an incorrect wheel, which can increase the risk of a crash.

Federal Motor Vehicle Safety Standard (FMVSS) 571.110 S4.3.3 "Additional Labeling Information for Vehicles Other Than Passenger Cars" requires "Each vehicle shall show the size designation and, if applicable, the type designation of rims (not necessarily those on the vehicle) appropriate for the tire appropriate for use on that vehicle, including the tire installed as original equipment on the vehicle by the vehicle manufacturer" to be printed on the manufacturer label. Subject vehicles are equipped with a manufacturer label that is missing the size designation of the rims.

#### HOW DO I RESOLVE THIS IMPORTANT SAFETY ISSUE?

You may choose to apply the enclosed overlay label using the instruction as described on the enclosed instructions letter. Or if you prefer not to install the label yourself, simply contact your dealer to schedule a service appointment. FCA US LLC will repair your vehicle [2] free of charge (parts and labor). To do this, your dealer will apply the manufacturer label overlay with corrected information. The estimated repair time is 20 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. **Please bring the enclosed overlay label and this letter with you to your dealership.** 

# TO SCHEDULE YOUR <u>FREE</u> REPAIR, CALL YOUR CHRYSLER, DODGE, JEEP OR RAM DEALER TODAY

## WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit <u>www.fcarecallreimbursement.com</u> to submit your reimbursement request online. <sup>[3]</sup> Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations

FCA US LLC



Mr. Mrs. Customer 1234 Main Street Hometown, MI 48371

<sup>[1]</sup> If you no longer own this vehicle, please help us update our records. Call the FCA Recall Assistance Center at 1-800-853-1403 to update your information.

<sup>[2]</sup> If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or you can call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to safercar.gov.

<sup>[3]</sup> You can also mail in your original receipts and proof of payment to the following address for reimbursement consideration: FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.

This notice applies to your vehicle,

32B/NHTSA 24V-209

**LOGO** 

# **VEHICLE PICTURE**

#### YOUR SCHEDULING OPTIONS

- 1. RECOMMENDED OPTION
  Call your authorized Alfa Romeo
  dealership.
- 2. Call Alfa Romeo Premium Care at 1-866-932-3881. An agent can confirm part availability and help schedule an appointment.
- 3. Visit recalls.mopar.com, scan the QR code below, or download the Mopar Owner's Companion App.

**QR Code** 

Get access to recall notifications, locate your Alfa Romeo dealership, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity. The last eight characters of your VIN are provided above.

## **DEALERSHIP INSTRUCTIONS**

Please reference Safety Recall 32B.

# IMPORTANT SAFETY RECALL

#### Manufacturer label

Dear [Name],

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

FCA US LLC has decided that certain [2024 model year (GC) Alfa Romeo Tonale] vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 110 - Tire selection and rims.

It is extremely important to take steps now to repair your vehicle to ensure the safety of you and your passengers.

#### WHY DOES MY VEHICLE NEED REPAIRS?

Your vehicle [1] may have been built with a manufacturer label that is missing rim and tire size designation information. Relying on incorrect rim and tire size designation information can result in the use of an incorrect wheel, which can increase the risk of a crash.

Federal Motor Vehicle Safety Standard (FMVSS) 571.110 S4.3.3 "Additional Labeling Information for Vehicles Other Than Passenger Cars" requires "Each vehicle shall show the size designation and, if applicable, the type designation of rims (not necessarily those on the vehicle) appropriate for the tire appropriate for use on that vehicle, including the tire installed as original equipment on the vehicle by the vehicle manufacturer" to be printed on the manufacturer label. Subject vehicles are equipped with a manufacturer label that is missing the size designation of the rims.

#### HOW DO I RESOLVE THIS IMPORTANT SAFETY ISSUE?

You may choose to apply the enclosed overlay label using the instruction as described on the enclosed instructions letter. Or if you prefer not to install the label yourself, simply contact your dealer to schedule a service appointment. FCA US LLC will repair your vehicle <sup>[2]</sup> free of charge (parts and labor). To do this, your dealer will apply the manufacturer label overlay with corrected information. The estimated repair time is 20 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. **Please bring the enclosed overlay label and this letter with you to your dealership.** 

# TO SCHEDULE YOUR <u>FREE</u> REPAIR, CALL YOUR ALFA ROMEO DEALER TODAY

## WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit <a href="www.fcarecallreimbursement.com">www.fcarecallreimbursement.com</a> to submit your reimbursement request online. [3] Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations



Mr. Mrs. Customer 1234 Main Street Hometown, MI 48371

# SAFETY RECALL 32B - MANUFACTURER LABEL OWNER INSTRUCTIONS

# INSTALL THE MANUFACTURER OVERLAY LABEL BY FOLLOWING THE PROCEDURE BELOW:

1. Locate the manufacturer label on the vehicle driver side B-pillar (Figure 1).



Figure 1 – Locate Manufacturer Label Location

2. Obtain the **NEW** manufacturer overlay label for the vehicle.

NOTE: Only one overlay label will be supplied depending on your vehicle type. Please verify the overlay label is appropriate for the vehicle based on engine and tire size the vehicle is equipped with.

• If you believe you received an incorrect overlay label, please contact your dealer.

Overlay 1	If Plug-in Hybrid Electric Vehicle with 1.3L Engine and 225/55R18 tires Use overlay with GVWR of 2420 kg/5335 lb and 225/55R18 tires
	If vehicle is equipped with a 2.0L Engine and 225/55R18 tires Use overlay with GVWR of 2250 kg/4960 lb and 225/55R18 tires
	If vehicle is equipped with a 2.0L Engine and 235/40R20 tires Use overlay with GVWR of 2250 kg/4960 lb and 235/40R20 tires
	If vehicle is equipped with a 2.0L Engine and 215/60R17 tires Use overlay with GVWR of 2250 kg/4960 lb and 215/60R17 tires
Overlay 5	If Plug-in Hybrid Electric Vehicle with 1.3L Engine and 235/40R20 tires Use overlay with GVWR of 2420 kg/5335 lb and 235/40R20 tires
Overlay 6	If Plug-in Hybrid Electric Vehicle with 1.3L Engine and 235/45R19 tires Use overlay with GVWR of 2420 kg/5335 lb and 235/45R19 tires

- 3. Use isopropyl alcohol or window cleaner and a clean cloth to remove any wax, oil, dust, and debris from the existing manufacturer label.
- 4. Allow the isopropyl alcohol or window cleaner to fully evaporate before applying the overlay label.
- 5. Apply appropriate overlay label to the manufacturer label in the original position and with the same text orientation to correct the information (Figure 2).
- 6. Apply pressure to the entire surface of the manufacturer overlay label with firm overlapping strokes removing all wrinkles and air bubbles. Using a tool such as a squeegee is allowed.




Figure 2 – Install Manufacturer Overlay Label