



PETERBILT MOTORS COMPANY
 A **PRICOR** COMPANY
 1700 WOODBROOK STREET P.O. BOX 90208
 DENTON, TEXAS 76205-7864 DENTON TEXAS 76202-5208
 940-591-4000

IMPORTANT SAFETY RECALL INFORMATION



Issued in Accordance
 With Federal Law



PRESORTED
 FIRST-CLASS MAIL
 U.S. POSTAGE PAID
 CLEVELAND, OH
 Permit No. 469

IMPORTANT SAFETY RECALL

*****AUTO**ALL FOR AADC 440



000018
 T1 P1

24PBL

IMPORTANT SAFETY RECALL

SAFETY RECALL: 24PBL

IMPORTANT SAFETY RECALL

January 30, 2025

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Subject: Safety Recall: 24PBL - Bendix EC80 ABS ECU Incorrect Signal Processing
NHTSA: 24V915
Bendix Recall #: 24E-086
EXPIRATION DATE: NONE

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect, which relates to motor vehicle safety exists in certain Vehicle Model Year 2021-2025 Peterbilt chassis configured for trailer towing that were manufactured from 04/06/2020 through 12/06/2024.

Electronic noise and/or low signal strength on the Power Line Carrier (PLC) signal from a trailer to the Bendix EC80 ABS ECU could cause the ABS system to incorrectly process certain signals. This can lead to the Bendix EC80 ABS ECU setting faults, malfunctioning, or not operating. ABS faults could affect the operation of other ABS-connected systems such as Automatic Traction Control, Electronic Stability Control, Active Cruise Control, and/or Collision Mitigation System.

These faults could cause the ABS system to respond incorrectly to a stability or automated braking event, increasing the risk of a crash. The ABS warning lamp will be illuminated in the event of faults in the ABS system or when the ABS system stops operating.

What is the problem?	Bendix ABS ECU could incorrectly process signals.
What will your dealer do?	Dealers will update Bendix EC80 ABS ECU software.
What should you do?	Contact your Peterbilt Dealer to schedule an appointment for repair.

Peterbilt has initiated this recall to remedy the issue at no charge to you. Please contact your Peterbilt dealer to schedule an appointment for these services. To find your Peterbilt dealer, please visit the "Find a Dealer" link at www.Peterbilt.com or scan the QR code. When contacting your Peterbilt dealer, reference the Safety Recall number, NHTSA Recall Number, and VIN(s) listed in this letter. This repair may take up to 1 hour of labor depending on dealer scheduling.


If you require further information about this recall or experience any difficulty in making arrangements for this repair, please contact the Peterbilt Customer Experience Department at PB.Tech.Pubs.Dept@paccar.com.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner. Please send all known ownership and address changes to PBDiv.Warranty,Docs@paccar.com.

We apologize for any inconvenience this procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Michelle Ponsonby
Director of Customer Experience
Peterbilt Motors Company

Scan this QR code to open the
Peterbilt Dealer Locator.



Our records indicate that these vehicles are affected by 24PBL and are owned by [REDACTED]

