

 <b>Tesla, Inc.</b> Service Bulletin		<h2>Update Vehicle Software to Enlarge Visual Warning Indicators</h2>	
<b>SB-24-00-003</b> February 17, 2024			
<b>Classification</b>		<b>Section/Group</b>	<b>Mobile Service</b>
Recall Bulletin		00 - Inspection & Service	Can Perform (where permitted)
<b>Model</b>	<b>Year</b>	<b>Country/Region</b>	<b>Build Location</b>
Model S	2012 - 2023	United States, Mexico, South Korea, Puerto Rico	All
Model X	2016 - 2024		
Model 3	2017 - 2023		
Model Y	2019 - 2024		
Cybertruck	2024		
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

### Condition

On affected vehicles in the aforementioned markets, the letter font size of the Brake, Park, and Antilock brake system (ABS) visual warning indicators is smaller than the height required by the applicable safety standard.

### Correction

Inspect the vehicle software version and, if necessary, update the vehicle software to the version listed below or a later version, any of which increases the letter font size of the Brake, Park, and Antilock brake system (ABS) visual warning indicators to the height required by the applicable safety standard.

Correction Description	Correction	Time
Inspect Vehicle Software Version; No Update Necessary	S012400003	0.06
Inspect and Update Vehicle Software To Enlarge Visual Warning Indicators	S022400003	0.06

### Procedure

On the vehicle touchscreen, touch **Controls** (vehicle icon) > **Software**, and then scroll down to display the vehicle software version.

- If the vehicle is operating with the software version listed below or a later version, no further action is necessary. Use correction code S012400003.
- If the vehicle is operating with a software version earlier than listed below, update the software to the version listed below or a later version. Refer to service manual procedure 00020003:
  - [Legacy Model S Tegra software version 2022.8.10.17](#)
  - [Legacy Model S Intel Atom software version 2024.2.2.1](#)
  - [Palladium Model S software version 2024.2.2.1](#)
  - [Legacy Model X Tegra software version 2022.8.10.17](#)
  - [Legacy Model X Intel Atom software version 2024.2.2.1](#)
  - [Palladium Model X software version 2024.2.2.1](#)
  - [Model 3 software version 2024.2.2.1](#)
  - [Model Y software version 2024.2.2.1](#)
  - [Cybertruck software version 2024.2.2.1](#)

Use correction code S022400003.