

Technical information

Daimler Buses

TI No.: 86.10T24282A

Distribution list: D

Distribution date:

11.03.2024

Valid until: 31.12.2044

The point of contact is the Daimler Buses after-sales service in each country

Model: Tourrider USA

MODEL DESIGNATION 410840; 410850

(BM):

TITLE: Tourrider USA - Override flap of lift opens before end position

COMPLAINT

The outer override flap of the lift drops too soon.

CAUSE

The pressure sensor in the lift's hydraulic system is positioned incorrectly.

REMEDY

Convert the pressure sensor in accordance with the instructions attached.

MEASURE TYPE

The scope of the work is carried out as part of a safety recall (RC).

OPERATION TEXTS

Operation no.	Operation text	Working time/h	Comment
12-1989	Convert pressure sensor in lift hydraulic system	1.0	

The times apply for work at an hourly rate.

DEFECT NUMBER

Defect no.:	Designation
8691074	

CODEWORD

8610T24282

INTRODUCTION FROM VIN

WEBS404H8P3292505

WEBS50AH4R3400784

WARRANTY AND GOODWILL SETTLEMENTS

Field measure type RC: 100 % of costs will be accepted.

DB/MCC

pp.

Markus Fischer

DB/MCC-O

pp.

Philipp Funken

Attachments

- →: [Conversion instructions](#)

This document may contain confidential information. Distribution outside the production plant's distribution list is not permitted.

For information only. Subject to ongoing technical development. Not subject to the amendment service.