RECALL 24V265 / 2024-222 REMEDY INSTRUCTIONS



Make(s): CARDINAL & WILDCAT

Model(s): SEE BELOW Model Year(s): 2024

Concern:

Vehicles manufactured with a Turning Point Fifth-Wheel Hitch, which may allow up to 90° port and starboard turning under certain circumstances. Additionally, these vehicles were manufactured with a Lippert Rear Towing Hitch installed on the vehicle. Repair Code: RC-062-03-00-004532

Allotted Time: .30 HRS. Inspection Code: N/A Allotted Time: N/A

Photo(s) Required: NO

Prior Authorization Required: YES

Part(s) Kit Number: N/A Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN 2024 – CARDINAL: CAF23RK-RED, CAF25BH-RED, CAF26RD-RED & CAF27RB-RED CERTAIN 2024 – WILDCAT: WCF23RK-ONE, WCF25BH-ONE, WCF26RD-ONE & WCF27RB-ONE

STEP 1: LOCATE AREA ON THE DRIVERS SIDE PIN BOX SIDE PLATE THAT IS PERMINATLY ATTACHED TO THE CHASSIS (FIGURE 1);

• ENSURE TO LOCATE A SPOT AS TO NOT COVER UP ANY EXISTING STICKERS OR INFORMATION;

STEP 2: CLEAN THE AREA ON THE DRIVERS SIDE PIN BOX SIDE PLATE WITH ISOPROPYL ALCOHOL;

• CLEAN AN AREA AT MINUMIM THE SIZE OF THE STICKER;

STEP 3: APPLY STICKER TO THE DRIVERS SIDE PIN BOX SIDE PLATE;

STEP 4: LOCATE AN AREA ON THE REAR WALL DIRECTLY ABOVE THE RECEIVER HITCH (FIGURE 2);

- ENSURE TO LOCATE A SPOT AS TO NOT COVER UP ANY EXISTING STICKERS OR INFORMATION;
- IN THE AREA TO THE LEFT OR RIGHT OF THE EXISTING SICKERS ON THE REAR WALL, AS CLOSE TO CENTER AS PRACTIBLE;

STEP 5: CLEAN THE AREA ON THE REAR WALL WITH ISOPROPYL ALCOHOL;

CLEAN AN AREA AT MINUMIM THE SIZE OF THE STICKER;

STEP 6: APPLY STICKER TO THE REAR WALL;

