







Suburban Range and Slide-In Deactivate Lights

Bulletin Type:	Recall
Bulletin #(s):	24V-300 USA
	2024-250 Canada
Job Code(s):	9902606
Flat Rate(s):	9902606 .30 HR LED Backlight
	Deactivation

Publication Date:	May 2024
Make(s):	Starcraft
Model(s):	Starcraft GSL FW
Model Year(s):	2023


Incident:	Suburban Range and Slide-in Lights are inoperable
Affected Units:	2023 Starcraft GSL FW
Parts Kit: 24V-300	Parts Kit #: 24V-300
	Part Kit Contents: 1 - LED Backlight Deactivation Kit
Misc. Tools & Supplies:	Crimper, Crimp Caps
Parts Return Information:	N/A

Bulletin Type:	Recall
Bulletin #(s):	24V-299 USA 2024-251 Canada
Job Code(s):	9904606
Flat Rate(s):	9904606 .30 HR LED Backlight Deactivation

Publication Date:	May 2024
Make(s):	Highland Ridge
	Mesa Ridge TT, Mesa
	Ridge XLT FW, Open
Model(s):	Range Roamer, Open
	Range TT, Silverstar TT,
	Silverstar XLT TT
Model Year(s):	2022-2023

Incident:	Suburban Range and Slide-in Lights are inoperable
Affected Units:	2022-2023 Highland Ridge Mesa Ridge TT, Mesa Ridge XLT FW, Open Range Roamer, Open Range TT, Silverstar TT, Silverstar XLT TT
Parts Kit: 24V-300	Parts Kit #: 24V-300
	Part Kit Contents: 1 - LED Backlight Deactivation Kit
Misc. Tools & Supplies:	Crimper, Crimp Caps
Parts Return Information:	N/A

SUBURBAN RANGE AND SLIDE-IN DEACTIVATE LIGHTS INSTRUCTIONS



876 Broadway Street | Dayton, TN 37321 | 423.775.2131 | www.airxceil.com/rw/suburban

206346 Range and Slide-in Deactivate Lights Instructions

WARNING

This appliance is not intended for use by young children or infirm persons unless they have been adequately supervised by a responsible person to ensure they can use the appliance safely.

ensure they can use the appliance safely.

To prevent electrical shock and/or equipment damage, disconnect electrical power to the system at the main fuse or circuit breaker until installation is complete.

CAUTION

This electrical work must be performed by trained technicians only. Adhere to all local and national codes and ordinances. Take care when securing and routing wires so they do not short. Personal injury and/or property damage may occur.

This electrical work will disable the function of the red, white and oven lights.

- 1. Disconnect 12VDC power to the range.
- Remove the range main top by firmly pulling up at the front. Lift the main top free of the burner box clips and set aside.



Locate the red and black wires that connect to the coach wiring (Coach wiring color may vary). Cut this wire directly behind the connector using a pair of electrical cutters.





PN: 206346 4-2-2024

 Crimp the Crimp Caps(233759) to incoming 12V positive and negative to prevent lights from being reattached.



Locate and unplug the wires from the light switch on the front of the unit, Then remove the light switch by squeezing the locking tabs and replace with the plug provided in the kit (233754).



Replace the main top by engaging rear clips and pressing firmly on the front latch.



- 7. Close the glass cover (if equipped)
- 8. Reconnect 12VDC power.

Service

For any questions, please reach out to the Suburban service department using the contact information below

Suburban, An Airxcel Brand Service Department 676 Broadway Street Dayton, TN 37321 (574) 247-9235 Option 5

Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540