


RRC-82-24-001-1: Perform Headlamp Adjustment

Rivian Automotive, LLC has decided that certain model year 2023-2024 Rivian R1S, R1T, and EDV vehicles fail to conform to Federal Motor Vehicle Safety Standard FMVSS 108 (Lamp, reflective devices and associated equipment - §571.108 S10.14.6). Headlamps that are not aimed properly can result in insufficient illumination of the road while driving, which may increase the risk of a crash while driving at night. Pursuant to its recall determination, Rivian will check the headlamp adjustment on the affected vehicles and correct it, if necessary.

Document Type	Safety Recall Bulletin
Date	May 31, 2024
Affected Region(s)	USA, Canada
Affected Model(s)	R1T, R1S, EDV
Model Year(s)	2023 - 2024
Approximate Build Dates	April 2023 - March 2024
 Refer to Open Containments in ServiceOS to determine if this document applies to a specific vehicle.	
Vehicle System	82 - Lighting
Minimum Service Location	Service Center

Procedure

Perform: Headlamp Adjustment (refer to service manual procedure 821011019).

Labor Codes

Labor Code	Description
RRC822400100	RRC-82-24-001 not applicable
RRC822400101	Check headlamp aim, no adjustment required
RRC822400102	Check and adjust headlamp aim
Contact ServiceDocumentFeedback@rivian.com regarding labor codes and document content.	