

**May 31, 2024**

Version 5

**Safety Recall: 2018-20 Fit Audio Unit Software Update****This bulletin has been replaced by 24-081, dated May 31, 2024.**

If you did the repair indicated in this bulletin on or before May 31, 2024, use the warranty information below to file a claim.

**WARRANTY CLAIM INFORMATION**

<b>Operation Number</b>	<b>Description</b>	<b>Flat Rate Time</b>	<b>Defect Code</b>	<b>Symptom Code</b>	<b>Template ID</b>	<b>Failed Part Number</b>
0105A9	Update the audio unit system software.	0.3 hr	6DW00	PD200	A24005A	39171-T5R-A21

Skill Level: Repair Technician

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.