

RECALL 24V386 / 2024-308 REMEDY INSTRUCTIONS



Make(s): SABRE
Model(s): SRF32BHT
Model Year(s): 2024

Concern:
The egress window may not be located on an opposite wall (rear/drivers side).

Repair Code: RC-047-09-00-004549
Allotted Time: 1.00 HRS.
Inspection Code: RC-047-05-00-004548
Allotted Time: .10 HRS.

Photo(s) Required: YES, WINDOW TAG
Prior Authorization Required: YES
Part(s) Kit Number: F100606483
Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

INSPECTION:

STEP 1: LOCATE EGRESS WINDOW IN THE REAR OF THE VEHICLE;

- IF THE EGRESS WINDOW IS INSTALLED IN THE REAR WALL, CLAIM THE INSPECTION CODE;
- IF A NON-EGRESS WINDOW IS INSTALLED IN THE REAR WALL, MOVE ON TO THE REMEDY;
 - SUBMIT A PHOTO OF THE REAR WALL WINDOW INSTALLED SHOWING IT IS NOT AN EGRESS WINDOW;

REMEDY:

STEP 1: REMOVE THE NON-EGRESS WINDOW FROM THE REAR WALL AND DISCARD;

STEP 2: INSTALL THE EGRESS WINDOW IN THE REAR WALL OPENING;

- APPLY SEALANT AS NEEDED TO WINDOW FRAME;
- USE THIS WINDOWS SPECIFIC TRIM RING AND SCREWS TO REINSTALL
- APPLY CAP SEAL AS NEEDED

STEP 3: ENSURE TO LOCATE THE "EXIT" STICKER TO THE REAR WALL NEXT TO/AT THE IMMEDIATE TOP OR BOTTOM TO THE WINDOW SO IT IS VISABLE WITHOUT MOVING ITEMS;

STEP 4: CLAIM REPAIR CODE.