



Thor Motor Coach Recall Repair Instructions

Recall #	24V441 2024-437		
Description/Title:	OM/MG Emergency Exit Window		
Affected Product Line(s):	Certain Omni/Magnitudes with a Griddle under the emergency exit window		
Service Campaign # :	RC000307		
Repair Code:	Inspect with Repair: TMCRC80544V	Released Date:	8/1/2024
Time Allowed:	Inspect with Repair: 1.0	Document Revision:	A

Issue:

When using the outside Griddle option, the interior emergency exit window is partially blocked.

Tools:

Parts:

Kit # 0568392

Instructions:

- 1) Remove the current emergency egress window on the passenger side of the unit.
- 2) Adhere the supplied bulb seal to the window before installing.
- 3) Install the replacement window.
- 4) After the window is installed, use Geocel or similar sealant to seal around the exterior of the window.



Thor Motor Coach Recall Repair Instructions

