 <b>Tesla, Inc.</b> <b>Service Bulletin</b>		<h2>Replace LH and RH Sail Appliques</h2>	
<b>SB-24-12-006</b> July 2, 2024			
<b>Classification</b>		<b>Section/Group</b>	<b>Mobile Service</b>
Recall Bulletin		12 - Exterior Fittings	Can Perform (where permitted)
<b>Model</b>	<b>Model Year</b>	<b>Country/Region</b>	<b>Build Location</b>
Cybertruck	2024	United States	Giga Texas
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			


Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

### Condition

On certain Cybertruck vehicles, the left-hand (LH) or right-hand (RH) sail applique or adhesion may not have been installed according to specification, which may cause the sail applique to become loose or separate from the vehicle.

### Correction

Replace both LH and RH sail appliques.

 **NOTE:** If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time
Replace LH And RH Sail Appliques And Install Push Nuts	S012412006	0.30

	Part Number	Description	Quantity
<b>Parts Required</b>	1741538-00-F	BED SIDE APPLIQUE ASSEMBLY - LEFT HAND	1
	1741539-00-F	BED SIDE APPLIQUE ASSEMBLY - RIGHT HAND	1
	1025670-00-A	Push Nut 7.9x23.8MM Diameter	2
	1975264-00-A	Push Nut 6.2, STL, G0410	2

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

**Shop Supplies** SEAM ROLLER, SILICONE, 5"  
ERASER WHEEL

### Procedure

Replace the LH and RH sail appliques (refer to Service Manual procedure [1220126012](#) for the LH sail applique and [1220126022](#) for the RH sail applique).

 **CAUTION:** When installing the new sail applique, ensure the push nut is properly installed.