

RECALL 24V490 / 2024-374 REMEDY INSTRUCTIONS



Make(s): SALEM & WILDWOOD
Model(s): SEE BELOW
Model Year(s): 2024 - 2025

Concern:
Certain vehicles may not have been
manufactured with a secondary means of
egress.

Repair Code: RC-047-01-00-004582
Allotted Time: 2.50 HRS.
Inspection Code: RC-047-05-00-004581
Allotted Time: .10 HRS.

Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: F100627547
Part(s) Return: N/A

FIG. 1



FIG. 2



FIG. 3



FIG. 4



FIG. 5



RECALL 24V490 / 2024-374 REMEDY INSTRUCTIONS



Make(s): SALEM & WILDWOOD
Model(s): SEE BELOW
Model Year(s): 2024 - 2025

Concern:
Certain vehicles may not have been
manufactured with a secondary means of
egress.

Repair Code: RC-047-01-00-004582
Allotted Time: 2.50 HRS.
Inspection Code: RC-047-05-00-004581
Allotted Time: .10 HRS.
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: F100627547
Part(s) Return: N/A

FIG. 6



FIG. 7



FIG. 8




FIG. 9



RECALL 24V490 / 2024-374 REMEDY INSTRUCTIONS



Make(s): SALEM & WILDWOOD
Model(s): SEE BELOW
Model Year(s): 2024 - 2025

Concern:
Certain vehicles may not have been manufactured with a secondary means of egress.

Repair Code: RC-047-01-00-004582
Allotted Time: 2.50 HRS.
Inspection Code: RC-047-05-00-004581
Allotted Time: .10 HRS.

Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: F100627547
Part(s) Return: N/A

FIG. 10



FIG. 11



END OF REMEDY & PHOTOS FOR SMT167RBK, SMT167RBKX, WDT167RBK, WDT167RBKX ONLY