

# SAFETY RECALL

NORTH AMERICA

## Right Side Airbag Connector Partially Engaged



Reference: 71B / NHTSA 24V-516

FCA US LLC



Remedy available for  
2021-2022 (KL) Jeep Cherokee

Template Version 1.0

Revision	Edition	Detail
0	July 2024	Initial Version.

### SYMPTOM DESCRIPTION

The right Side Airbag Inflatable Curtain (SABIC) connector on 13 of the above vehicles may not have been properly secured during assembly. An improperly secured SABIC connector may prevent the airbag from deploying in certain types of crashes. A SABIC that does not deploy may increase the risk of occupant injury in certain types of crashes.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.214 and 571.226 requires SABIC airbag deployment during certain crash events.

### SCOPE

This recall applies only to the above vehicles.

### REPAIR TO BE PERFORMED

All vehicles in this recall have been remedied. There is no action required.

### OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail.

### ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations  
FCA US LLC.