



Thor Motor Coach Recall Repair Instructions

Recall #	24V-666 2024-520		
Description/Title:	2024 Transit LP Heatshield		
Affected Product Line(s):	Certain MY 2024 Palladium & Talavera motorhomes		
Service Campaign # :	RC000314		
Repair Code:	Inspect with Repair: TMCRC80501V	Document Date:	MM/DD/YYYY
Time Allowed:	Inspect with Repair: 1.0	Document Revision:	A

Issue:

It has been discovered that on Certain MY 2024 Palladium and Talavera Motorhomes, the LP tank heat shield is the incorrect size.

Parts:

Kit #0570452



- 1 -Heat Shield
- 3 -Bolts
- 6 -Washers
- 3 -Locknuts

Instructions:


1. Align heatshields together and predrill holes in existing heatshield



Thor Motor Coach Recall Repair Instructions





2. Bolt (#2) together on exhaust side, nuts (#4) to be placed on LP tank side of heat shield (#1).



BOM		
NO	QTY	DESCRIPTION - W x L (GRAIN)
1	1	HEAT SHIELD, LP TANK (TFM8895)
2	3	BOLT, HEX 1/4-20 x 1-1/2 GRADE 5
3	6	WASHER, .25 SCREW SIZE SS (0184253)
4	3	LOCKNUT, 1/4-20 NYLON INSERT



Thor Motor Coach Recall Repair Instructions



Thor Motor Coach
1-877-500-1020
NHTSA Recall # 24V-666
Transport Canada Recall # 2024-520