



Noncompliance Turn Lights (Inspection)

Classification		Parts Kit Required	
Recall 189 – Remedy C Inspect	Part # NA	Description	NA
Condition			
Some Winnebago vehicles have front turn signal lamps that do not meet the luminous lens area requirements, resulting in non-compliance with Federal Motor Vehicle Safety Standard FMVSS No. 108, regarding lamps and reflective devices. The smaller lens may hinder visibility for other drivers, thereby increasing the risk of a collision.			
Correction			
Inspect for Noncompliant Turn Signal Lights on the front end of the vehicle. If the Noncompliant Turn Signals exist on the vehicle, please order the Recall Kit RC7955-26-789, follow Remedy A Work Instructions and file the claim for that repair. If the vehicle does NOT have these Noncompliant Turn Signals and has other compliant lenses instead, file a claim and follow the standard warranty process of filing for Inspection Only.			
Disclaimer: If you have any questions, please contact the Winnebago Industries Technical Service Department by calling 1-866-653-4329 or by email: techservice@wgo.net . This document is confidential and is intended for dealer use only.			

EXAMPLES OF THE NONCOMPLIANT TURN LIGHTS



EXAMPLES OF COMPLIANT TURN LIGHTS

