

RECALL 24V883 REMEDY INSTRUCTIONS



Make(s): CEDAR CREEK
Model(s): CRT40DE
Model Year(s): 2025

Concern:
The axles and tire may be inadequate for the vehicle.

Repair Code: RC-006-01-00-004649
Allotted Time: 2.00 HRS.
Inspection Code: N/A
Allotted Time: N.A
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: N/A
Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

STEP 1: REPLACE THE 6,000 LBS. AXLES (2) WITH 7,000 LBS. AXLES (2)

STEP 2: REPLACE THE ST235/80R16/E TIRE AND RIM COMBINATION WITH A ST235/85R16/G TIRE AND RIM COMBINATION;

STEP 3: CLEAN THE AREAS OF THE FEDERAL PLACARD LOCATIONS AND INSTALL NEW FEDERAL PLACARD, COVERING THE CURRENT FEDERAL PLACARD;