


## RECALL 24V895 REMEDY INSTRUCTIONS

 <b>FOREST RIVER</b>	Make(s): MANY, SEE BELOW Model(s): MANY, SEE BELOW Model Year(s): 2025	Repair Code: RC-058-01-00-004650 Allotted Time: .50 HRS. Inspection Code: N/A Allotted Time: N/A
	Concern: The triple square taillamp may experience excessive heat, which may lead to premature taillamp failure.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: F100121680 Part(s) Return: NO, FIELD DESTROY

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN 2025 – CONCORD: CNC321DSF

CERTAIN 2025 – ENTOURAGE: E1C320LVI & E1C340BHI

CERTAIN 2025 – FREELANDER: FLC21QSSC3500, FLC26DSF45, FLC26MBF45 & FLC31MBF45

CERTAIN 2025 – LEPRECHAUN: LPC220XGF35, LPC230FSF35, LPC260DSF, LPC260MBF45, LPC298KBF & LPC319MBF

STEP 1: LOCATE THE REAR TAIL LAMPS ON THE REAR WALL;


- REMOVE AND DISCARD;



STEP 2: INSTALL THE REPLACEMENT TAIL LAMPS IN THE SAME LOCATION;



## RECALL 24V895 REMEDY INSTRUCTIONS

	Make(s): MANY, SEE BELOW Model(s): MANY, SEE BELOW Model Year(s): 2025	Repair Code: RC-058-01-00-004650 Allotted Time: .50 HRS. Inspection Code: N/A Allotted Time: N/A
	Concern: The triple square taillamp may experience excessive heat, which may lead to premature taillamp failure.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: F100121680 Part(s) Return: NO, FIELD DESTROY

STEP 3: TEST TAIL LAMPS FOR ALL FUNCTIONALITIES;

STEP 4: CLAIM REPAIR CODE.