

SAFETY RECALL

NORTH AMERICA

Seat Thorax Airbag Connector



Reference: B3B / NHTSA 24V-897

FCA US LLC



Remedy available for

2022 – 2024 (WL) Jeep Grand Cherokee

2021 – 2024 (WL) Jeep Grand Cherokee L

Template Version 1.0

Revision	Edition	Detail
0	December 2024	Initial Version.

SYMPTOM DESCRIPTION

The front seat Side Air Bag (SAB) squib connector on about 15 of the above vehicles may be improperly secured. FMVSS 571.214 requires front seat SAB deployment during certain crashes. An improperly secured front seat SAB squib connector may prevent the airbag from deploying in those crashes. A front seat SAB that does not deploy when intended may increase the risk of occupant injury in certain types of crashes.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 214 - Side impact protection.

SCOPE

This recall applies only to the above vehicles.

REPAIR TO BE PERFORMED

All vehicles in this recall have been remedied. There is no action required.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified by first class mail.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA US LLC.