



August, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2024 Maverick has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number** 24S27 - 2022-24 Maverick Rear Position Lamp May Become Inoperable  
**and Description:**

**What is the issue?** The Body Control Module (BCM) was improperly calibrated and may falsely detect a current overload on one or both taillamp circuits. If this occurs, one or both of the rear taillamps may stop functioning during a drive cycle.

Taillamps that fail to illuminate can cause reduced visibility in dark conditions, which may increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Augusto de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2024 Maverick las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 24S27 - Luz de posición trasera puede dejar de funcionar en vehículos Maverick 2022-24

**¿Cuál es el problema?** El módulo de control de la carrocería (BCM) se calibró incorrectamente y puede detectar falsamente una sobrecarga de corriente en uno o ambos circuitos de las luces traseras. Si esto ocurre, una o ambas luces traseras pueden dejar de funcionar durante un ciclo de conducción.

Las luces traseras que no se iluminan pueden reducir la visibilidad en condiciones de oscuridad, lo que puede aumentar el riesgo de un accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).


Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0020082 A / 000000000000536 / 536



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

