



August, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2020 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **24S35 - 2020-24 Aviator RVC Screen Flicker**

**What is the issue?**

On your vehicle, your mobile phone may produce electromagnetic interference while in-use. If it is placed in the console area while the vehicle is in reverse, it can cause the rearview camera image to appear distorted or flicker, jump, or scroll.

A distorted or flickering rearview camera image while reversing can reduce visibility behind the vehicle, increasing the risk of a crash.

You should refrain from mobile phone usage while reversing until you have your vehicle serviced. This will prevent this condition from occurring.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [lincoln.com/support](https://lincoln.com/support).

Thank you for your attention to this very important matter.

Augusto de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2020 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **24S35 - Parpadeo de la pantalla RVC Aviator 2020-24**

**¿Cuál es el problema?**

En su vehículo, su teléfono móvil podría producir interferencias electromagnéticas mientras está en uso. Si se coloca en el área de la consola mientras el vehículo está en reversa, puede hacer que la imagen de la cámara trasera parezca distorsionada o parpadee, salte o se desplace.

Una imagen de la cámara trasera distorsionada o parpadeante en reversa puede reducir la visibilidad detrás del vehículo, lo cual aumenta el riesgo de choque.

Debe abstenerse de usar el teléfono móvil mientras conduce en reversa mientras no haya realizado el servicio del vehículo. Esto evitará que ocurra esta condición.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](https://lincoln.com/support).

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0002042 A / 000000000000560 / 560



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

