



December, 2024

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2024 Mustang has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **24S36 - Underhood Fires**
and Description:

What is the issue?

On your vehicle, the hydraulic clutch pressure line may be improperly secured to a fastener on the dash panel. A line with improper retention may contact hot exhaust components and melt, leaking hydraulic fluid.

A hydraulic clutch line that leaks may result in an inability to change gears. Depending on the vehicle speed and gear, your engine may stall. A loss of drive power increases the risk of a crash.

If leaked hydraulic fluid accumulates near a hot surface, you may observe smoke and experience an engine compartment fire. An engine compartment fire increases the risk of injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

December, 2024

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2024 Mustang las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **24S36 - Incendio bajo el cofre**

¿Cuál es el problema?

En su vehículo, la línea de presión del embrague hidráulico puede estar asegurada de manera incorrecta a un sujetador en el panel de instrumentos. Una línea con retención inadecuada puede entrar en contacto con componentes de escape calientes y derretirse, lo que provocará una fuga de líquido hidráulico.

Una línea de embrague hidráulico que tiene fugas puede provocar la imposibilidad de cambiar de velocidad. Dependiendo de la velocidad y la velocidad del vehículo, el motor se podría parar. Una pérdida de la potencia de impulsión aumenta el riesgo de sufrir una colisión.

Si el fluido hidráulico filtrado se acumula cerca de una superficie caliente, es posible que observe humo y experimente un incendio en el compartimento del motor. Un incendio en el compartimento del motor aumenta el riesgo de lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0000129 A / 000000000001137 / 1137



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼



▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼