



March, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2023 Transit has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **24S46 - Transit Trail EPAS Anti-Rotation Ground Concern**  
**and Description:**

**What is the issue?**            The Electric Power Assisted Steering (EPAS) ground cable eyelet's substrate is exposed to environmental conditions and is susceptible to corrosion, which may result in an intermittent or complete loss of power to the EPAS motor and Power Steering Control Module (PSCM).

An intermittent or complete loss of power to the EPAS motor and PSCM may result in a loss of power steering assist, and may increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Marzo de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2023 Transit las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **24S46 - Transit Trail - Problema de tierra anti-rotación de EPAS**

**¿Cuál es el problema?**            El sustrato de la arandela del cable de tierra de la dirección asistida eléctrica (EPAS) está expuesto a las condiciones ambientales y es susceptible a la corrosión, lo que puede provocar una pérdida intermitente o completa de potencia en el motor de la EPAS y el módulo de control de la dirección hidráulica (PSCM).

Una pérdida intermitente o completa de potencia en el motor EPAS y el PSCM puede provocar una pérdida de asistencia de la dirección asistida y puede aumentar el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).


Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0009571 A / 000000000000606 / 606



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

