



February, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2024 Transit has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number** 24S53 - Cert Label and IVM FGAWR  
**and Description:**

**What is the issue?** On your vehicle, the front Gross Axle Weight Rating (GAWR) may be incorrectly listed as 2,100 kilograms (4630 pounds) on the incomplete vehicle information label and in the incomplete vehicle manual. The actual front GAWR rating for your vehicle is 1,873 kilograms (4130 pounds).

Frequent and extended use of an affected vehicle loaded to a front GAWR above design capacity may lead to a front steering knuckle failure. If a front steering knuckle fails, partial loss of steering control may occur, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Febrero de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2024 Transit las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 24S53 - Etiqueta de certificación y FGAWR de IVM

**¿Cuál es el problema?** En su vehículo, el peso bruto nominal del eje delantero (GAWR) podría aparecer incorrectamente como 2100 kilogramos (4630 libras) en la etiqueta de información de vehículo incompleto y en el manual del vehículo incompleto. El peso bruto nominal del eje delantero GAWR real de su vehículo es 1,873 kilogramos (4130 libras).

El uso frecuente y prolongado de un vehículo afectado cargado hasta un GAWR delantero por encima de la capacidad de diseño podría provocar una falla en el mango de dirección delantero. Si falla un mango de dirección delantero, se podría producir una pérdida parcial del control de la dirección, lo que aumenta el riesgo de accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0001743 A / 000000000001112 / 1112



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

