



March, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2024 Maverick has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **24C33 - 2024 Maverick 2nd Row Tether Anchor Torque**  
**and Description:**

**What is the issue?**            In affected vehicles, a child seat top tether anchorage bolt may have incomplete thread engagement and as a result, may not meet the strength requirements for child restraint anchorage systems.

A tether anchorage point that does not meet the strength requirements for child restraint anchorage systems could result in anchorage point failure, increasing the risk of injury in the event of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Marzo de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2024 Maverick las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **24C33 - Maverick 2024 - Par de apriete del anclaje de la correa de la 2ª fila**

**¿Cuál es el problema?**            En los vehículos afectados, es posible que un tornillo de anclaje de sujeción superior del asiento para niños tenga una conexión de rosca incompleta y, como resultado, podría no cumplir con los requisitos de resistencia para los sistemas de anclaje del asiento de sujeción para niños.

Un punto de anclaje que no cumpla con los requisitos de resistencia para los sistemas de anclaje del sistema del asiento de sujeción para niños podría provocar una falla del punto de anclaje, lo que aumenta el riesgo de sufrir lesiones en caso de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).


Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0039108 A / 000000000000603 / 603



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼  
REMOVE THESE SIDE EDGES FIRST

