



August, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2024 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 24S70 - 2024-25 F150, 2024 Expedition and Navigator 3.5L Engine Cup Plug Dislodged -
and Description: Safety

What is the issue? It is possible that your vehicle may have a misaligned cup plug, located at the rear of the engine, which may result in a rapid oil leak.

An oil leak in the presence of an ignition source such as hot engine or exhaust components, can increase the risk of a fire. In addition, the loss of oil can result in loss of motive power, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Augusto de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2024 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 24S70 - F150 2024-25, Expedition y Navigator 2024 motor 3.5L Tapón de copa desprendido - Seguridad

¿Cuál es el problema? Es posible que su vehículo tenga un tapón de copa desalineado, ubicado en la parte trasera del motor, lo que puede provocar una fuga de aceite repentina.

Una fuga de aceite en presencia de una fuente de encendido, como un motor caliente o componentes del escape, puede aumentar el riesgo de incendio. Además, la pérdida de aceite puede provocar una pérdida de fuerza motriz, lo que aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0776764 A / 000000000000604 / 604



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

