

24KWJ: Meritor Front Steer Drive Axle Hub Lubrication

 [Edit](#)  [Clone](#)

Number

24KWJ / NHTSA# 24V903 / TC# 2024-729

Supplier

Meritor

Description

Meritor Front Steer Drive Axle Hub Lubrication

Date

12/12/2024

What's New

Interim Safety Recall

Certain Kenworth model T380 and T480 chassis equipped with a Meritor 10-16K or 18-23K Front Steer Drive Axle have been identified as possibly having insufficient wheel bearing grease. Insufficient lubrication in the wheel bearing may cause the wheel hub to overheat and become damaged, which may increase the risk of fire. The driver may observe noise, excessive steering play, and/or smoke from the front wheel.

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Introduction

Interim Safety Recall

Certain Kenworth model T380 and T480 chassis equipped with a Meritor 10-16K or 18-23K Front Steer Drive Axle have been identified as possibly having insufficient wheel bearing grease. Insufficient lubrication in the wheel

bearing may cause the wheel hub to overheat and become damaged, which may increase the risk of fire. The driver may observe noise, excessive steering play, and/or smoke from the front wheel.

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Resolution

Interim Safety Recall

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[24KWJ Chassis List](#)

[24KWJ US Customer Letter](#)

[24KWJ CAN Customer Letter](#)