

24KWK: PACCAR 20k Steer Axle Steer Arm and Tie Rod Arm Bolt Torque

 [Edit](#)  [Clone](#)

Number

24KWK / NHTSA# 24V908 / TC# 2024-732

Description

PACCAR 20k Steer Axle Steer Arm and Tie Rod Arm Bolt Torque

Date

12/12/2024

What's New

Interim Safety Recall

Certain Kenworth model T480, T800, T880, and W990 equipped with a PACCAR 20k Steer Axle have been identified as having steer arm and/or tie rod arm fasteners that may be improperly torqued and can be at risk of failing. If both fasteners, in either steering arm or tie rod bracket fail, there may be a loss of steering control, which could increase the risk of a crash.

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Introduction

Interim Safety Recall

Certain Kenworth model T480, T800, T880, and W990 equipped with a PACCAR 20k Steer Axle have been identified as having steer arm and/or tie rod arm fasteners that may be improperly torqued and can be at risk of failing. If

both fasteners, in either steering arm or tie rod bracket fail, there may be a loss of steering control, which could increase the risk of a crash.

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Situation

46 (35 U.S. and 11 Canada) Model Year 2024-2025 T480, T800, T880, and W990 chassis built from 01/11/2023 through 2/22/2024 and equipped with a PACCAR 20k Steer Axle.

Resolution

Interim Safety Recall

At this time, parts are not available to complete the necessary repairs. This bulletin will be updated when parts become available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[24KWK Chassis List](#)

[24KWK US Customer Letter](#)

[24KWK CAN Customer Letter](#)

Authored By JK