

EQUIPMENT RECALL N964 – DEFENDER RAISED AIR INTAKE

EQUIPMENT SAFETY RECALL N964 – RAISED AIR INTAKE	
AFFECTED MODELS / PART NUMBER	20-25MY Defender Part Number: VPLEP0543
VOLUME AFFECTED	Potential number of parts in USA 485 and 26 in Canada.
REPAIR	A concern has been identified with the accessory raised air intake where there is a dimensional tolerance mismatch between the lower fixing on the raised air intake and the body A-pillar to which it mounts. This tolerance mismatch can result in inadequate attachment force between the raised air intake and the vehicle.
REPAIR TIME	Up to 0.6 hrs + DIDO
CAMPAIGN LAUNCH	The Recall Admin notification bulletin was posted on TOPIx on December 19th, 2025. The repair bulletin was published on Feb 11th, 2025
NOTES	Accessory sales are blocked. Retailers must stop installing this accessory part and stop selling vehicles with the accessory part already installed. ACTION: Retailers are requested to search their records and identify and report all vehicles where they have completed the raised intake accessory installation or parts sales for intake part VPLEP0543. Retailers are requested to return unused parts stock to their PDC and follow all instructions in the bulletin.