

RECALL N778 – REAR SURROUND CAMERA BEZEL – WATER INGRESS

SAFETY RECALL N778 – REAR SURROUND CAMERA BEZEL – WATER INGRESS	
AFFECTED MODELS	18–22MY L405 Range Rover and L494 Range Rover Sport
VOLUME AFFECTED	US 58,729 CAN 9,463
REPAIR	A concern has been identified where the reversing camera may display a poor image or no image at all because of water ingress into the camera housing/bezel. Lack of display of the rear-view camera image may result in the driver being unaware of objects or pedestrians behind the vehicle increasing the risk of a crash. The rear camera will be removed, inspected, replaced if the inspection fails and reinstalled with a new seal.
REPAIR TIME	0.6 hrs + DIDO
CAMPAIGN LAUNCH	Retailer Admin Bulletin: published on February 1st, 2024 Repair bulletin pending parts supply estimated availability mid-February 2024.
NOTES	Clients will be notified via mail on or before March 8th, 2024