

## RECALL N778 – REAR SURROUND CAMERA BEZEL – WATER INGRESS

SAFETY RECALL N778 – REAR SURROUND CAMERA BEZEL – WATER INGRESS	
AFFECTED MODELS	18–22MY L405 Range Rover and L494 Range Rover Sport
VOLUME AFFECTED	US 58,729 CAN 9,463
REPAIR	A concern has been identified where the reversing camera may display a poor image or no image at all because of water ingress into the camera housing/bezel. Lack of display of the rear camera image may result in the driver being unaware of objects or pedestrians behind the vehicle increasing the risk of an accident. The rear camera will be removed, inspected, replaced if the inspection fails and reinstalled with a new seal.
REPAIR TIME	0.6 hrs. + DIDO
CAMPAIGN LAUNCH	Repair bulletin published on February 22nd, 2024, for 18-22MY Range Rover only. The bulletin will be re-issued to add Range Rover Sport model when the additional Nitto foam seals required for that model are available to be ordered by retailers. Timing estimated at Mid-April. <b>Affected Range Rover Sport vehicles <u>must not be</u> repaired until the bulletin is re-issued with that specific repair instruction.</b>
NOTES	Clients will be notified via mail on or before March 8th, 2024