

## RECALL H468 – TRACTION BATTERY BUSBAR FIXINGS

SAFETY RECALL H468 – TRACTION BATTERY BUSBAR FIXINGS	
AFFECTED MODELS	19-20MY I-PACE
VOLUME AFFECTED	2 US ONLY
REPAIR	A concern has been identified where the fasteners for the battery module to module electrical connecting busbars may not be sufficiently secure, which under some circumstances could result in arcing at the busbar to module connection point. Arcing will generate heat which may lead to a thermal overload condition. Retailers will need to inspect the fixings and replace/repair as required.
REPAIR TIME	Repair time circa. 16 hours
CAMPAIGN LAUNCH	Retailer admin bulletin issued on February 22nd, 2024 Repair Launched March 20 <sup>th</sup> , 2024.
NOTES	Please refer to the warranty portal to identify affected vehicles which must be repaired at the next service visit.  Clients will be notified via mail on or before March 28th, 2024