

## Safety Recall 24TA04

The two head restraints on the 60% portion of the rear, fold down seats in this vehicle may have poor welds which can affect head restraint performance, increasing the risk of injury during certain collisions.

Please call an authorized Toyota dealer for a FREE repair.

Until the remedy is performed, Toyota recommends passengers do not occupy the rear middle or rear right seat in the vehicle.

Visit [Toyota.com/recall](https://toyota.com/recall) or the Toyota app for more information.