

URGENT SAFETY RECALL NOTICE

Your 2022 RAM RAM 3500 PROMASTER C-A LR 159 EXT is under recall for Seatbelt Buckle Sensor.

To schedule your recall repair contact your dealership or the FCA US Recall Team at [1-800-853-1403](tel:1-800-853-1403).

Recall notice issued to:

Vehicle information:

VIN

2022 RAM RAM 3500 PROMASTER C-A LR 159 EXT

Recall information: 02B/NHTSA 24V-129

Visit recalls.mopar.com for more information or call the FCA US Recall Team at [1-800-853-1403](tel:1-800-853-1403)

Details of the Recall

The driver seat belt buckle on your vehicle may have been built with an incorrect switch sense magnet. Suspect vehicles may incorrectly activate the warning system indicating that the seat belt is unlatched when it is latched. Failure to detect whether an occupant is buckled can impede the seatbelt warning system from deactivating when the belt is properly fastened, potentially leading to reduced seat belt use which can increase the risk of injury in certain crashes.

FCA US LLC will repair your vehicle free of charge (parts and labor). To do this, your dealer will inspect and, if necessary, replace the driver seat belt buckle. The estimated repair time is 45 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience.

How do I schedule my **FREE** repair?

- ◆ Simply contact your Chrysler, Jeep®, Dodge or RAM dealer right away to schedule a service appointment.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you

for your attention to this important matter.

Customer Assistance/Field Operations

FCA US LLC Team

[1-800-853-1403](tel:1-800-853-1403)

recalls.mopar.com