

## RECALL H475 – REAR LAMP DOUBLE TICK TOCK

SAFETY RECALL H475 – REAR LAMP DOUBLE TICK TOCK	
AFFECTED MODELS	21-24MY I-PACE
VOLUME AFFECTED	US 2015 CA 219
REPAIR	A concern has been identified on vehicles where the electrical loads should make the double speed tick-tock and tell-tale flash at double rate in an electrical failed state. The absence of warning of electrical failure of the rear turn signal indicator may result in the driver being unaware of a failure. An update to the Car Configuration File (CCF) is required.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	Launched March 14th, 2024
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which must be repaired before sale and delivery. Sold vehicles must be repaired at the next service visit. <b>As of March 18th, 360 new affected vehicles are in retailer inventory.</b>