

RECALL H484 – I-PACE TRACTION BATTERY THERMAL OVERLOAD – ELEVATED RISK

SAFETY RECALL H484 – I-PACE TRACTION BATTERY THERMAL OVERLOAD – ELEVATED RISK	
AFFECTED MODELS	19MY I-PACE
VOLUME AFFECTED	US 258 CA 84
REPAIR	Battery packs manufactured between March 1, 2018, and May 31, 2018, are exposed to multiple technical issues shown to contribute to an elevated risk of thermal overload. Vehicles already modified through safety recall H441 are less likely to experience thermal overload but to remove all doubt for this population, this safety recall is being undertaken. The repair procedures are being developed and will be published when further details are available.
REPAIR TIME	TBA
CAMPAIGN LAUNCH	Retailer Notification Bulletin initially published March 8th, 2024. Version 3 published March 13 th , 2024
NOTES	Please refer to the warranty portal to identify affected vehicles. As directed in version 3 of the H484 bulletin, no battery cell replacements should be carried out at this time on any vehicle included in this campaign.