

RECALL H481 – 2021-2024 E-PACE BRAKE PAD WEAR INDICATOR INOPERATIVE

SAFETY RECALL H481 – BRAKE PAD WEAR INDICATOR INOPERATIVE

AFFECTED MODELS	21-24MY E-PACE
VOLUME AFFECTED	US 2842 CA 102
REPAIR	As a result of an incorrect setting in the Car Configuration File, the brake pad wear indicator does not display where brake pads have worn to a condition where the indicator lamp should display. This is a non-compliance with the requirements of CMVSS 135 and FMVSS 135, Light Vehicle Brake Systems. Affected vehicles require a car configuration file update.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	Admin notification bulletin published March 28th, 2024. Repair bulletin is expected mid-April
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which must be repaired before sale and delivery. Sold vehicles must be repaired at the next service visit. As of April 9th, 76 new affected vehicles open in this recall are in retailer inventory which must be held pending repair