

## RECALL H481 – 21-24MY E-PACE BRAKE PAD WEAR INDICATOR INOPERATIVE

## SAFETY RECALL H481 – BRAKE PAD WEAR INDICATOR INOPERATIVE

|                 |                                                                                                                                                                                                                                                                                                                                                                        |
|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AFFECTED MODELS | 21-24MY E-PACE                                                                                                                                                                                                                                                                                                                                                         |
| VOLUME AFFECTED | US 2842 CA 102                                                                                                                                                                                                                                                                                                                                                         |
| REPAIR          | As a result of an incorrect setting in the Car Configuration File, the brake pad wear indicator does not display where brake pads have worn to a condition where the indicator lamp should display. This is a non-compliance with the requirements of CMVSS 135 and FMVSS 135, Light Vehicle Brake Systems. Affected vehicles require a car configuration file update. |
| REPAIR TIME     | 0.2 hrs + DIDO                                                                                                                                                                                                                                                                                                                                                         |
| CAMPAIGN LAUNCH | Admin notification bulletin published March 28th, 2024.<br>Repair bulletin launched on April 16th, 2024                                                                                                                                                                                                                                                                |
| NOTES           | Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which must be repaired before sale and delivery.<br>Sold vehicles must be repaired at the next service visit.<br>As of May 7th, 43 new affected vehicles open in this recall are in retailer inventory.                                               |