

RECALL N901 – REAR SURROUND CAMERA BEZEL – WATER INGRESS

SAFETY RECALL N901 – REAR SURROUND CAMERA BEZEL – WATER INGRESS

AFFECTED MODELS	18–22MY L494 Range Rover Sport
VOLUME AFFECTED	US 22,268 CAN 5,153
REPAIR	A concern has been identified where the reversing camera may display a poor image or no image at all because of water ingress into the camera housing/bezel. Lack of display of the rear camera image may result in the driver being unaware of objects or pedestrians behind the vehicle increasing the risk of an accident. The rear camera will be removed, inspected, replaced if the inspection fails and reinstalled with a new seal.
REPAIR TIME	0.6 hrs. + DIDO
CAMPAIGN LAUNCH	Launched on May 29th, 2024
NOTES	Clients will be notified via mail before July 19th, 2024. Initial supplies of Nitto foam have been proactively shipped directly to all retailers based on estimated vehicle repair volume.