

**RECALL H506/N908 – INGENIUM I6 3.0L OIL FILTER ELEMENT CAP -RENEW**

## SAFETY RECALL N908/H506 – INGENIUM I6 3.0L OIL FILTER ELEMENT CAP - RENEW

|                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AFFECTED MODELS | 24MY F-PACE<br>24MY Range Rover, Range Rover Sport, Range Rover Velar, Defender, and Discovery                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| VOLUME AFFECTED | N908: US 2011 CAN 149 H506: US 149 CAN 3                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| REPAIR          | A concern has been identified where the incorrect specification of plastic was used to manufacture the oil filter housing. The incorrect specification plastic housing will, over time and with vehicle use, crack allowing oil to leak out onto the engine and into the engine compartment. An oil leak under pressure in this area could result in oil contact with hot components on the engine, which may result in a fire. Additionally, oil may leak onto the road surface posing a skid hazard to other road users, especially two wheeled vehicles, and increase the risk of a crash. Replacement of the oil filter and filter housing are required. |
| REPAIR TIME     | 0.2 hrs + DIDO                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| CAMPAIGN LAUNCH | Quarantine Notification released on June 11th, 2024<br>Recall Repair Bulletin launched on June 14th, 2024<br>Full requirements for parts have been shipped to retailers.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| NOTES           | Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory.<br>Retailers are also requested to continue to make their own proactive client contacts and to prioritize getting the remaining affected vehicles into the workshop to expedite service repairs.<br>To support this, VIN lists by retailer have been provided to the CSMM's and RPMs<br><b>Open VIN count: USA 167 CAN 24</b><br>JLR NA are now initiating their 3rd round of customer texts, emails and 2nd round of direct mailing for the remaining open VIN.                                                                           |