

Questions and answers
Lamborghini Huracan EVO Spyder model year 2024.



“Front Frame Bracket”

■ What is the issue with the affected vehicles?

In the affected vehicles, on the front structural member assembly, a bracket which is relevant for crash protection according to FMVSS208 criteria "Paragraph S5.1.2. Unbelted test", may have been mounted on the wrong side of the vehicle. As such, these vehicles fail to meet the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection".

■ What is the cause of this condition?

Error during the manual assembly step of the component.

■ What effect does the condition have?

In the event of a crash, an incorrectly installed frame bracket may not provide adequate protection to an unbelted passenger, increasing the risk of injury.

■ Which vehicles are affected?

Lamborghini model line Huracan EVO Spyder model year 2024.

■ How many vehicles are affected in USA?

39 units.

■ Which VIN numbers are affected?

From ZHWUT4ZF3RLA26136 to ZHWUT4ZF6RLA28947; manufactured from November 2023 to July 2024.

■ What exactly needs to be updated on the car?

Dealers will inspect the parts and if necessary, remove the wrongly installed bracket and reassemble it on the correct side, free of charge.

■ How long will the repair work take?

Normally, the operation can take approximately 2 (two) hours.

■ Can customers continue to drive the cars?

Yes, however we encourage them to contact their authorized Lamborghini dealer to schedule an appointment to have this important free update performed as soon as possible.

■ Will Automobili Lamborghini S.p.A. bear the costs of the repair work?

The costs of this campaign will be borne entirely by Automobili Lamborghini S.p.A.

■ Where can I have the repair work carried out ?

Any authorized Lamborghini dealer and Service point worldwide.

■ Is it necessary to make an appointment at the workshop?

Yes, customer should contact an authorized Lamborghini dealer or Service point.