

SAFETY RECALL N759 – FRONT KNUCKLE CRACKING

SAFETY RECALL N759 – FRONT KNUCKLE CRACKING	
AFFECTED MODELS	2014-2016 MY RANGE ROVER
VOLUME AFFECTED	16759 USA
REPAIR	A concern has been identified on certain 2014 to 2016 model year Range Rover vehicles where the front suspension upper knuckle joint could develop a crack. In extreme cases where a crack in the front suspension knuckle has developed, this may lead to detachment of the upper suspension arm. Vehicles will require inspection and either the additional of a supporting bracket or the replacement of the suspension knuckle casting
REPAIR TIME	TBC
CAMPAIGN LAUNCH	A recall admin bulletin was published November 21 st to notify all retailers and affected VIN are flagged in the warranty portal. The required parts have been ordered and it expected to be several months before there is sufficient stock of all required parts to enable publication of the full repair bulletin.
NOTES	