

SAFETY RECALL N946 – REAR CAMERA WATER INGRESS

SAFETY RECALL N946– REAR CAMERA WATER INGRESS	
AFFECTED MODELS	2022-2023 MY RANGE ROVER
VOLUME AFFECTED	11,961 US 616 CAN
REPAIR	A concern has been identified where, on certain Range Rover vehicles, water could get into the rear-facing tailgate mounted camera. This water ingress can cause a distorted image, or no image at all, to be displayed on the touchscreen. The repair procedures is being developed and will be advised in due course.
REPAIR TIME	TBC
CAMPAIGN LAUNCH	Retailers were notified by a Recall Admin Bulletin published January 8 th , 2025.
NOTES	Retailers are required to Quarantine affected new vehicles that are within your control and not release affected vehicles for new vehicle sale pending completion of the rework. The repair procedures and any required parts and/or software are not currently available. A Safety Recall repair bulletin will be published when all repair procedures and all required parts and/or software are available.