

SAFETY RECALL N946 – REAR CAMERA WATER INGRESS

SAFETY RECALL N946– REAR CAMERA WATER INGRESS	
AFFECTED MODELS	22-23MY Range Rover (L460)
VOLUME AFFECTED	11,961 US 616 CAN
REPAIR	A concern has been identified where, on certain Range Rover vehicles, water could get into the rear-facing tailgate mounted camera. This water ingress can cause a distorted image, or no image at all, to be displayed on the touchscreen. Rear camera will need to be replaced.
REPAIR TIME	Up to 0.5 hr + DIDO
CAMPAIGN LAUNCH	Retailers were notified by a Recall Admin Bulletin published January 8th, 2025. A launch stock of parts and the safety recall repair bulletin are expected w/c March 17th.
NOTES	Clients have received an interim notification informing them of the recall on February 14th, 2025. A 2nd notification will be mailed after the recall is launched, requesting clients make service appointments at their retailer.